

Safety Issue Type: Recalls

May 27 2022 NHTSA Campaign Number: 22V382000

Powertrain Control Module Malfunction

A rearview camera or reverse light that is disabled reduces the driver's rear view, increasing the risk of a crash. Disabled driver assist features (traction control, forward collision warning, blind spot warning, cross traffic indicator) may increase the risk of a crash.

NHTSA Campaign Number 22V382000

Manufacturer Ford Motor Company

Components POWER TRAIN

Potential Number of Units Affected 25032

Summary

Ford Motor Company (Ford) is recalling certain 2019-2020 Mustang vehicles equipped with 5.0L engines and manual transmissions. The Powertrain Control Module (PCM) may broadcast an unintended faulted signal to the modules controlling the reverse camera, reverse light, and driver assist features, which may disable all of these functions.

Remedy

Dealers will update the PCM software, free of charge. Owner notification letters are expected to be mailed June 13, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S37.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (2)

Vehicle

MAKE	MODEL	YEAR
FORD	MUSTANG	2019-2020

Associated Documents (3)

Defect Notice 573 Report

RCLRPT-22V382-6344.PDF 216.535KB

<https://static.nhtsa.gov/odi/rcl/2022/RCLRPT-22V382-6344.PDF>

Recall Acknowledgement

RCAK-22V382-9821.pdf 645.561KB

<https://static.nhtsa.gov/odi/rcl/2022/RCAK-22V382-9821.pdf>

Manufacturer Notices(to Dealers,etc) - Dealer Bulletin re NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Safety Recall 22S37

Certain 2019 - 2020 Model Year Mustang 5.0L Vehicles with a Manual Transmission Powertrain Control Module Reprograming

RCMN-22V382-0242.pdf 246.231KB

<https://static.nhtsa.gov/odi/rcl/2022/RCMN-22V382-0242.pdf>